OSA 1651-64 22 March 1964

TRACEANING FOR THE RECORD

SUBJECT: Shipping Plan

FURFOCE: Shipment of Automation Equipment from

Readquarters to

25X1A

SCOPE:

the items it is necessary to start preparation for this move approximately one week prior to the actual move. A timing schedule for the entire operation is shown in enclosure #2. This timing schedule is for the departure of the equipment from Headquarters only, and does not cover any portion of the move once it is leaded aboard the aircraft.

25X1A

- %. To ensure proper operation of the MAI 3500 plotter the Washington representative of the washing will be requested to furnish one company engineering representative for complete check-out one week prior to shipment. This visit will also include instruction for Automation Division personnel in the preparation of the plotter for shipment. This will include the tie-down of movable components and the removal of easily damaged parts. The parts that are removed will be packed in cartons by members of the Automation Div-The plastic cover for the plotter will not be installed . due to the possibility of its being lost or damaged enroute. If required, wooden skids will be installed. These skids are to be manufactured by the Headquarters Carpenter Shop and installed on the console side of the plotter. They are necessary for the possibility of turning the plotter on its side to facilitate entrance into doors too narrow for the width of the plotter.
 - for shipment the rest of the items will be collected and checked for proper padding and packing. If additional padding or cartons are required these will be obtained from shipping section of Headquarters. As the items are readied a packing

	1
DOCUMENT NO.	
No chaird	X
[] 256 CL 10 1	
D1.550. 82	2011
Maxi River	20.0

Approved For Release 2001/08/16 CIA-RIPP81B00961R000100170001-7

SECRET

: MAR 1651-64

list will be prepared for each carton and distributed as follows:

Copy

- 1 Packed inside the carton.
- % Stored in an envelope fastened securely to the outside of the carton.
- To be used for info package hand-carried to Area.
- 4 For Material/OSA.
- AUTO/OSA files.
- 4. when all items to be shipped have been packed a Bill of lading will be made with each item being numbered correspending to its number on the Bill of Lading. On the day of movement the personnel assigned to the move from Automation Division will arrive at Hendquarters in time to start coordinating the movers and their equipment by 0700%. move should be made following the timing schedule as outlined in enclosure #2.
- . Once the equipment has been loaded on the trucks/ vans the movers supplied by Hendquarters will be relieved. The two personnel from Automation Division and one from MD/05A will then follow the vans to Andrews AFB. Transportation for these personnel will be by private conveyance.
- Upon arrival at the aircraft the loading of the equipment will be under the direct supervision of the loadmaster assigned to the aircraft. After the vans/trucks have been unloaded they will be released to their individual units and the AUTO/DIV and MD/OSA personnel will return to normal who will accompany the duties, except for shipment.

	Automation	Division	personne	1 -	and	
					commercial a	
for	. They	will arriv	ve at	in s	ifficient tim	樓
prior to	arrival of	enrgo ai	rcraft to	arrange :	for unloading	
and trans	sporting of	load to	proper lo	cation on	the base.	

25X1A

25X1A

25X1A

25X1A

25X1A


(用A 1851-64

25X1A

25X1A

to concerning this shipment will be referred in that order, at Head-quarters, ext. 4260 or Red-1870.

25X1A



inclosures - 6

#1 - Shipping List

#2 - Timing

74 - Equipment Requirements at Readquarters

#4 - Packing Instructions

#5 - Telephone Numbers and Personnel

#6 - Moving Instructions

25X1A

AUTO/FA/(SA

Matribution:

A - AUTO/FA/OBA

1 - D/FA/OSA

1 - (3)MMO/08A

2 - AD/OSA

1 - CC/08#

1 - 66/06A

1 - RB/08A

SECRET

Declosure #1

SKIPPING LIST

- A. One MAI 3500 Plotter Board.
- 1. One Carton MAI Paper Tape Reader.
- J. One Carton Mil Plotter Arm.
- 4. One Carton RAI Operating Manuals.
- . One carton SAI Spare Parts.
- d. Gae MG-13. (Facked in Carton)
- 7. One carton Flexowriter Paper.
- 3. One carton Paper Tape.
- it. one carton Mod M.
- 10. One carton Firden Teledata.
- 11. One carton Friden Paper Guide.
- 12. One carton Friden flexowriter.
- 13. One carton Friden Flexowriter Stand.
- 14. One carton EAL Flotter Equipment.

The total cube of the shipment is 231 cu. ft.
The cube and wgt of the plotter is 80 cu. ft. and 2000
the respectively.

aclosure #2

PIMIM:

- Warch 27 and 30 All equipment that can be prepared for shipment will be made ready during this period.
- 25X1A

 25
 - time check to ensure that proper preparation has been made. This is to include the preparation of a complete Bill of Lading so that a complete record will be made of the shipment.
 - Administration Branch of the Production and Administration Branch of Automation Division will be utilized for supervision in transporting the equipment from the 5B2817 Headquarters to the Loading Dock, Headquarters.
 - Administration Tranch of Automation Division will supervise the moving of equipment from 582817, Headquarters to the Loading Dock, Hqs. and the loading of this equipment on the trucks and/or vans.
 - April 1 (0900) Loading will be completed and the trucks/vans will depart for Andrews AFB. The personnel who are conveyence.
 - April 1 (1000) Loading of the equipment on the aircraft will
 - April 1 (1100) All equipment will be loaded.
 - April 1 (1200) Aircraft will depart Andrews APD.

SEGRET

Enclosure #3

BUILDMENT REQUIREMENTS AT READQUARTERS

- 1. Flat bed hand truck for moving numerous cartons and boxes.
- 2. Covered moving van with associated blankets and tie-down ropes or straps. (Winimum of 36 blankets and 24 ropes required)
- 3. High-lift bed truck with padding and ropes required for accement of the plotter from Headquarters to the aircraft.
- If the moving van is not equipped with either a highlift bed or tailgate a fork lift will be required for loading at Andrews.
- one hand truck will be required for the movement of the EG-13 rack. (Similiar to a refrigerator dolly)
- in Hooden skids to be furnished by Carpenter Shop, Eqs for use on the side of the plotter table. These skids should be attached to the console side of the plotter before departing Automation Division, but if there is a space limitation on either the high-lift truck or the sircraft they will be removed and carried as a separate item. The hardware necessary for their attachment to the plotter will be provided by the Carpenter Shdp, Headquarters.

SECRET

Anclosure #4

PACKING INSTRUCTIONS

in a special box. This box is located in Automation Division at the present time. The tracing paper for the plotter will be shipped inside it's proper drawer on the diotter board.

The oil will be removed from the vacuum pump of the board.

may other parts requiring tie-down within the plotter board will be secured under the direction of an MAI engineering representative.

- 2. Paper tape reader will be packed in a cardboard carton.
- 3. Two cartons of Friden equipment are still packed in their original containers as received from the factory and it is golt that they need no further padding.
- 4. The paper guide for the Friden Flexowriter is still packed in its original carton but does require some additional padding in addition to being marked with FRAGILE signs.
- The Friden Teledate will require a separate carton and will need sufficient padding to protect it during transit.
- 6. The telephone company's Mod-H will require packing.
- 7. One carton of Screenline Paper and one carton of paper tape for the Friden Teledata will be sent. These will not require any packing.
- 8. One carton of instruction and maintenance books will be included in the RAI shipment.
- 3. One carton of spare parts for the EAI Plotter will be included.
- 10. One KG-13 rack will be included. Due to its size it will be impossible to place this item in any sort of a con-tainer-rack whise called a prevent damage during transit.
- 11. EG-13 will be placed in a carton and packed securely for transit. This item will be the responsibility of the Communications Division, OSA.

Englosure #5

25X1A

TELEPHONE NUMBERS AND PERSONNEL



SEGRET

Anclosure as

MOVING INSTRUCTIONS

AUTO/FA. Production Branch will furnish two men to supervise and assist in moving the equipment from the Automation Division on the 5th floor. Hqs to the loading dock and thence to the vehicles. They will then follow the wehicles to Andrews AFB where they will again assist in the unloading of the equipment from the vehicles to the aircraft.

Hendquarters Support will furnish three movers to be used in moving the equipment from the 5th floor to the loading lock and then on to the vehicles.

The Control Center will furnish the necessary load-masters for loading the equipment on the mireraft.

Saterial Division will furnish one supervisor for the overall guidance during the move.